



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Carnarvon	Inlet	CN3/001	Carnarvon Town Beach	2011-2015	59	220	C	994	119	Assessment Required	Fair	Amber	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/002	Carnarvon Town Beach (2)	2013-2015	33	55	B	700	12	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/003	Facsine Beach	2011-2015	51	45	B	96	34	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/004	Before Yacht Club	2011-2015	48	50	B	700	20	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/005	Yacht Club	2013-2015	33	30	A	140	12	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/045	Fascine Jetty	2011-2015	50	16	A	50	25	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Carnarvon	Ocean	CN3/046	Pelican Point Beach	2013-2015	34	8	A	38	16	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	5



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Exmouth	Canal	EX3/057	Canal Nr Bridge Horwood Side	2010-2015	49	18	A	58	19	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Exmouth	Harbour	EX3/050	Small Boat Harbour - Boat Ramp	2010-2015	44	45	B	118	31	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Exmouth	Ocean	EX3/051	Exmouth Town Beach	2010-2015	44	85	B	203	47	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Esperance	Harbour	ES3/030	Bandy Creek Harbour	2011-2015	53	380	C	1750	322	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Esperance	Ocean	ES3/031	James St Groyne	2011-2015	52	105	B	254	56	Moderate - F/U	Good	Green	Collect 10 stormwater drain samples	13
Shire of Esperance	Ocean	ES3/032	Port Authority Beach	2011-2015	51	75	B	164	45	Moderate - F/U	Good	Green	Collect 10 stormwater drain samples	13
City of Albany	Harbour	AC3/007	Emu Beach - Oyster Harbour							Assessment Required	Not Avail			13
City of Albany	Ocean	AC3/008	Ellen Cove (Jetty) - Middleton Beach							Assessment Required	Not Avail			13
City of Albany	Ocean	AC3/009	Boatshed Beach - Princess Royal Harbour							Assessment Required	Not Avail			13
City of Albany	Ocean	AC3/010	Frenchman Bay							Assessment Required	Not Avail			13

Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Denmark	Inlet	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	2012-2013	26	45	B	700	10	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	2012-2015	41	150	B	573	77	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	2012-2015	41	800	D	4034	480	Assessment Required	Not Avail	Red	Provide DoH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/055	Wilson Inlet - Springdale Beach 6	2012-2013	25	100	B	333	52	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Denmark	River	DK3/054	Denmark River - Berridge Park	2012-2015	41	1200	D	1978	407	Assessment Required	Not Avail	Red	Provide DoH Sanitary Inspection Report	13
City of Greater Geraldton	Ocean	GE3/001	Town Beach Jetty	2010-2015	54	85	B	2527	23	High - F/U	Fair (a)	Amber	Collect 10 stormwater drain samples	13
City of Greater Geraldton	Ocean	GE3/003	Point Moore North	2010-2015	53	80	B	220	42	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	Ocean	GE3/005	Separation Point	2010-2014	42	150	B	300	73	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	Ocean	GE3/006	Back Beach	2010-2015	50	70	B	700	25	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
City of Greater Geraldton	Ocean	GE3/008	Marina North	2010-2015	54	2	A	22	14	Moderate - F/U	Good (a)	Green	Collect 10 stormwater drain samples	5
City of Greater Geraldton	Ocean	GE3/010	Saint Georges	2010-2015	55	55	B	700	30	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	Ocean	GE3/012	Sunset Beach - Triton Place	2012-2015	32	85	B	426	40	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Greater Geraldton	Ocean	GE3/021	Pages Beach North	2010-2015	53	240	C	574	112	Moderate - F/U	Poor	Red	Collect 10 stormwater drain samples	13
City of Greater Geraldton	Ocean	GE3/022	Tarcoola Beach	2010-2015	50	110	B	547	54	Very Low - F/U	Very Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	Ocean	GE3/023	Greenough Beach	2010-2015	49	32	A	105	20	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	Ocean	GE3/026	Drummonds Cove	2010-2014	37	30	A	81	26	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	River	GE3/024	Greenough River Mouth	2010-2015	53	130	B	700	47	High - F/U	Fair (a)	Amber	Collect 10 rainfall (within 24-48hrs) samples	13
City of Greater Geraldton	River	GE3/025	Ellendale Pool	2010-2015	52	390	C	445	132	High - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Irwin	Marina	IR3/080	Marina (Boat Ramp)	2010-2015	29	2	A	17	10	Assessment Required	Very Good	Green	Provide DoH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/001	Nunns Pool	2010-2015	29	105	B	800	48	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) & riverine samples	13
Shire of Irwin	Ocean	IR3/060	South Beach	2010-2015	29	45	B	138	25	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/070	Grannie's Beach	2010-2015	30	125	B	824	64	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Mandurah	Canal	MD3/330	Hall Park	2010-2015	74	32	A	83	27	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) & stormwater samples	13
City of Mandurah	Estuary	MD3/411	Eastern Foreshore	2013-2015	23	80	B	242	43	Assessment Required	Not Avail	Green		13
City of Mandurah	Marina	MD3/310	Marina Beach	2010-2015	88	2	A	23	13	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) & stormwater samples	5
City of Mandurah	Ocean	MD3/120	Falcon Beach	2010-2015	87	14	A	48	18	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	5
City of Mandurah	Ocean	MD3/155	Halls Head Parade	2010-2015	90	55	B	174	31	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
City of Mandurah	Ocean	MD3/315	Town Beach	2010-2015	87	22	A	166	10	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Mandurah	Ocean	MD3/410	North Port	2010-2015	88	7	A	37	17	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	5
Shire of Murray	Inlet	MY3/018	Coopers Mill	2010-2015	56	55	B	93	39	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Murray	River	MY3/002	Ravenswood Hotel - Murray River	2010-2015	64	250	C	2713	110	Very High - F/U	Poor	Red	Review SAC	13
Shire of Murray	River	MY3/003	Murray River Bend	2010-2015	64	200	B	355	89	Very High - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Murray	River	MY3/005	Pinjarra Boat Ramp	2010-2015	70	720	D	836	220	Very High	Very Poor	RED*	Management Action: Erect permanent warning Signs	5
Shire of Murray	River	MY3/007	Dwellingup Bridge	2010-2015	69	95	B	102	52	Very High - F/U	Fair (a)	Amber	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Murray	River	MY3/008	Delta Drive	2010-2015	64	110	B	17516	52	Very High - F/U	Fair (a)	Amber	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Murray	River	MY3/009	Lucie Hunter Park	2010-2015	69	310	C	8042	280	Very High - F/U	Poor	Red	Review SAC	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Murray	River	MY3/014	Baden Powell (2) Steps	2010-2015	86	560	D	774	192	Assessment Required	Not Avail	Red	Provide DoH Sanitary Inspection Report	13
Shire of Murray	River	MY3/020	The Clansman	2011-2015	51	70	B	132	43	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Murray	River	MY3/021	Scarp Pool	2011-2015	51	55	B	96	39	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Waroona	Lake	WR3/001	Drakesbrook Dam / Lake Moyanup							Assessment Required	Not Avail			13
Shire of Waroona	Lake	WR3/002	Waroona Dam / Lake Navarino	2008-2014	14	170	B	1223	94	Assessment Required	Not Avail	Green		13
City of Bunbury	Harbour	BC3/001	Jetty Bath West	2010-2015	64	60	B	4639	30	Moderate	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Bunbury	Ocean	BC3/012	Koombana Beach	2010-2015	62	14	A	47	20	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Bunbury	Ocean	BC3/017	Surf Club Beach	2010-2015	63	2	A	19	10	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	5
City of Bunbury	Ocean	BC3/018	Hungry Hollow	2010-2015	62	2	A	17	12	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	5
City of Bunbury	Ocean	BC3/025	Ski Beach	2010-2015	62	14	A	51	10	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13

Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
City of Busselton	Ocean	BN3/023	Margaret Street Beach (Site 8)	2010-2015	56	115	B	252	59	Moderate - F/U	Good	Green	Collect 10 rainfall (24-48hrs) & riverine samples	13
City of Busselton	Ocean	BN3/024	Scout Beach (Site 6)	2010-2015	57	130	B	13087	61	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
City of Busselton	Ocean	BN3/025	Forth Street Beach (Site 7)	2010-2015	57	140	B	656	73	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
City of Busselton	Ocean	BN3/028	Busselton Jetty Ocean 9	2010-2015	56	370	C	763	155	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Augusta-Margaret River	Inlet	AM3/023	Hardy Inlet - Turner Caravan Park	2010-2015	67	350	C	586	138	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/012	Gnarabup Beach (Jetty)	2010-2015	66	145	B	711	75	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/014	Gracetown Beach	2010-2015	67	70	B	252	35	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/016	Flinders Bay - Redman Brook	2010-2015	67	60	B	474	18	Moderate - F/U	Good	Green	Collect 10 rainfall & riverine samples	13
Shire of Augusta-Margaret River	River	AM3/001	Margaret River - Canoe Landing	2010-2015	64	260	C	440	108	Assessment Required	Not Avail	Amber	Provide DoH Sanitary Inspection Report	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Augusta-Margaret River	River	AM3/001	Margaret River - Rivermouth	2010-2015	13	190	B	229	79	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	River	AM3/006	Margaret River - Barrett St Weir	2010-2015	66	95	B	137	53	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	River	AM3/044	Margaret River - Rendall Cl Weir	2014-2015	12	2	A	19	13	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Capel	Ocean	CP3/001	Forrest Beach	2010-2015	49	660	D	2559	345	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Capel	Ocean	CP3/002	Peppermint Grove Beach	2010-2015	49	45	B	700	10	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Capel	Ocean	CP3/003	Minninup Beach	2010-2015	49	155	B	351	75	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Capel	Ocean	CP3/004	Dalyellup Beach	2010-2015	49	65	B	700	10	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Capel	River	CP3/005	Preston River - Boyanup	2010-2015	49	2800	D	1721	503	High	Very Poor	RED*	Management Action: Erect permanent warning signs	5
Shire of Capel	River	CP3/006	Capel River - Mallokup Bridge	2010-2015	48	380	C	562	142	High - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Collie/ DPaW	Reservoir	CI3/001	Potters Gorge - Wellington Dam							Low	Not Avail	Green		13
Shire of Collie/ DPaW	River	CI3/002	Honeymoon Pool - Collie River							Moderate - F/U	Not Avail	Amber	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Harvey	Ocean	HA3/020	Myalup Beach	2010-2015	30	2	A	17	10	Assessment Required	Not Avail	Green	Provide DoH Sanitary Inspection Report	13
Shire of Harvey	Ocean	HA3/021	Binningup Beach	2010-2015	30	45	B	700	10	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Harvey/ DPaW	Lake	HA3/027	Lake Brockman Boat Ramp	2014-2015	10	24	A	140	10	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) & riverine samples	13
Shire of Harvey/ DPaW	Reservoir	HA3/026	Harvey Dam Boat Ramp	2014-2015	10	70	B	214	36	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Dandaragan	Harbour	DA3/006	Jurien Boat Harbour Beach (West)	2010-2015	43	65	B	165	38	Moderate - F/U	Good	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Dandaragan	Harbour	DA3/007	Jurien Boat Harbour Beach (East)	2010-2015	44	34	A	95	24	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Dandaragan	Ocean	DA3/013	Dobbyn Park Beach	2010-2015	40	18	A	59	19	Moderate - F/U	Good (a)	Green	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of Dandaragan	Ocean	DA3/015	Cervantes - Swimming Beach	2013-2015	15	45	B	139	28	Assessment Required	Not Avail	Green		13



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples Rqd 2015-2016
Shire of Dandaragan	Ocean	DA3/016	Cervantes - Jetty/Boat Ramp	2013-2015	15	36	A	140	10	Assessment Required	Not Avail	Green		13
Shire of Gingin	River	GG3/001	Moore River - Mouth Beach							Assessment Required	Not Avail		Provide DoH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/002	Moore River - Caravan Park							Assessment Required	Not Avail		Provide DoH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/003	Moore River - Boat Ramp							Assessment Required	Not Avail		Provide DoH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/010	Moore River Desert Boardwalk							Assessment Required	Not Avail		Provide DoH Sanitary Inspection Report	13
Shire of West Arthur/ DPaW	Lake	AW3/001	Lake Towerrinning - Jetty 1	2011-2015	25	1350	D	19012	1410	Moderate - F/U	Poor	Red	Collect 10 rainfall (within 24-48hrs) samples	13
Shire of West Arthur/ DPaW	Lake	AW3/002	Lake Towerrinning - Caravan Park	2013-2015	15	740	D	894	228	Assessment Required	Not Avail	Red	Provide DoH Sanitary Inspection Report	13