

Regional Recreational Waters Bacterial Monitoring Program - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
AM3/001	Augusta-Margaret River	Margaret River (Canoe Landing)	2009-2012	37	290	C	543	121	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Amber	14
AM3/002	Augusta-Margaret River	Margaret River Rivermouth	2006-2010	9	85	B	112	50	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	
AM3/006	Augusta-Margaret River	Margaret River - Barrett St Weir	2008-2012	37	175	B	237	77	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Amber	15
AM3/008	Augusta-Margaret River	Gnarabup - Gas Bay Beach (near WWTP)	2009-2012	37	55	B	225	27	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	14
AM3/012	Augusta-Margaret River	Gnarabup Beach (Jetty)	2009-2012	37	230	C	1527	134	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Amber	14
AM3/014	Augusta-Margaret River	Gracetown Beach	2009-2012	37	130	B	3080	63	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	14
AM3/016	Augusta-Margaret River	Flinders Bay (Redman Brook)	2009-2012	37	40	A	113	27	Moderate	Rainfall	Collect 10 rainfall & riverine samples	Good (a)	Green	14
AM3/021	Augusta-Margaret River	Molloy Island Caravan Park	2009-2012	37	45	B	96	35	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	14
AM3/023	Augusta-Margaret River	Hardy Inlet (Turner Caravan Park)	2009-2012	37	290	C	499	120	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Amber	14
AM3/033	Augusta-Margaret River	Margaret River (Rope Swing)	2008-2012	32	8	A	38	18	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
BC3/001	Bunbury	Jetty Bath West	2007-2012	42	75	B	700	31	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
BC3/012	Bunbury	Koombana Beach	2007-2012	41	70	B	208	37	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
BC3/017	Bunbury	Surf Club Beach	2007-2012	39	38	A	140	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
BC3/018	Bunbury	Hungry Hollow	2007-2012	42	30	A	89	23	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
BC3/025	Bunbury	Ski Beach	2009-2012	39	40	A	140	21	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13

Regional Recreational Waters Bacterial Monitoring Program - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
BN3/023	Busselton	Margaret St Beach (Site 8)	2010-2012	30	120	B	297	61	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) & riverine samples	Good	Green	13
BN3/024	Busselton	Scout Camp Beach (Site 6)	2009-2012	33	32	A	94	22	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
BN3/025	Busselton	Forth St Beach (Site 7)	2009-2012	33	125	B	414	63	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
BN3/028	Busselton	Busselton Jetty (Site 9)	2010-2012	30	270	C	1750	104	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
CP3/001	Capel	Forrest Beach	2009-2012	33	410	C	2554	256	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
CP3/002	Capel	Peppermint Grove Beach	2009-2012	33	45	B	700	10	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
CP3/003	Capel	Minningup Beach	2009-2012	32	135	B	353	67	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
CP3/004	Capel	Dalyellup Beach	2009-2012	32	26	A	140	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
CP3/005	Capel	Preston River (Boyanup)	2010-2012	22	4150	D		440	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very Poor	Red	
CP3/006	Capel	Capel River (Mallokup Bridge)	2010-2012	21	620	D	1512	269	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very Poor	Red	13
DA3/006	Dandaragan	Jurien Harbour Beach (West)	2007-2012	27	50	B	145	28	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
DA3/007	Dandaragan	Jurien Harbour Beach (East)	2007-2012	28	22	A	140	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	13
DA3/013	Dandaragan	Dobbyn Park Beach	2009-2012	27	2	A	140	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	13
DK3/050	Denmark	Ocean Beach Caravan Park	2012	15	20	A	140	11	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
DK3/051	Denmark	Yacht Club Gazebo	2012	15	170	B	563	86	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13

Regional Recreational Waters Bacterial Monitoring Program - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
DK3/053	Denmark	Rivermouth Caravan Park	2012	15	1400	D	3463	586	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Red	13
DK3/054	Denmark	Denmark River - Berridge Park	2012	15	740	D	1584	298	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Red	13
DK3/055	Denmark	Springdale Beach	2012	15	130	B	1322	66	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
ES3/030	Esperance	Bandy Creek Harbour	2011-2012	18	560	D	2515	310	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
ES3/031	Esperance	James St Groyne	2011-2012	18	40	A	93	32	Moderate	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
ES3/032	Esperance	Port Authority Beach	2011-2012	18	24	A	63	26	Moderate	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
GE3/001	Greater Geraldton	Town Beach Jetty	2009-2012	31	125	B	6219	58	High - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Fair (a)	Amber	13
GE3/003	Greater Geraldton	Point Moore North	2009-2012	31	75	B	229	40	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GE3/005	Greater Geraldton	Separation Point	2009-2012	29	150	B	700	99	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
GE3/006	Greater Geraldton	Back Beach	2009-2012	29	50	B	145	29	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
GE3/008	Greater Geraldton	Marina North	2009-2012	31	2	A	17	12	Moderate	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
GE3/010	Greater Geraldton	Saint Georges Beach	2009-2012	32	125	B	562	63	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GE3/026	Greater Geraldton	Drummond Cove	2009-2012	27	18	A	57	21	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
GE3/021	Greater Geraldton	Pages Beach North	2009-2012	31	460	C	1825	243	Moderate	Stormwater	Provide DoH stormwater drain monitoring results	Poor	Red	13
GE3/022	Greater Geraldton	Tarcoola Beach	2009-2012	29	140	B	1671	76	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13

Regional Recreational Waters Bacterial Monitoring Program - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
GE3/023	Greater Geraldton	Greenough Beach	2009-2012	26	50	B	700	19	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GE3/024	Greater Geraldton	Greenough River Mouth	2009-2012	29	50	B	86	38	High - F/up	Rainfall	Provide DoH Sanitary Inspection Report	Fair (a)	Red	13
GE3/025	Greater Geraldton	Ellendale Pool	2009-2012	28	330	C	415	119	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
GE3/012	Greater Geraldton	Sunset Beach (Triton Pl)	2011-2012	11	55	B	700	46	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
HA3/020	Harvey	Myalup Beach	2009-2012	11	22	A	140	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
HA3/021	Harvey	Binningup Beach	2009-2010	11		A			Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
IR3/001	Irwin	Nunns Pool	2009-2012	20	10	A	43	18	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	15
IR3/060	Irwin	South Beach	2009-2012	20	85	B	401	39	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	15
IR3/070	Irwin	Grannie's Beach	2009-2012	21	150	B	1904	84	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	15
IR3/080	Irwin	Marina (Boat Ramp)	2009-2012	20		A			Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	15
MD3/120	Mandurah	Falcon Beach	2007-2012	91	16	A	54	19	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MD3/155	Mandurah	Halls Head Parade	2007-2012	94	22	A	72	18	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MD3/310	Mandurah	Marina Beach	2007-2012	92	5	A	31	15	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
MD3/315	Mandurah	Town Beach	2007-2012	91	12	A	54	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MD3/330	Mandurah	Hall Park	2007-2012	92	26	A	67	26	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13

Regional Recreational Waters Bacterial Monitoring Program - Site Status Overview: 2006-2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
MD3/410	Mandurah	North Port	2007-2012	92	26	A	66	26	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MY3/002	Murray	Ravenswood Hotel	2007-2012	59	200	B	292	86	Very High	Animals	Review Sanitary Inspection Category	Fair (a)	Amber	13
MY3/003	Murray	Murray Bend	2007-2012	58	260	C	7318	113	Very High	Animals	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
MY3/005	Murray	Pinjarra Boat Ramp	2007-2012	60	840	D	733	219	Very High	Septics Tanks	Follow-up Re: Management Actions	Very Poor	Red	13
MY3/007	Murray	Dwellingup Bridge	2007-2012	59	260	C	286	96	Very High	Animals	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
MY3/008	Murray	Delta Drive	2007-2012	58	240	C	22285	149	Very High	Animals	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
MY3/009	Murray	Lucie Hunter Park	2006-2011	58	200	B	5281	147	Very High	Animals	Collect 10 rainfall (24-48hrs) samples	Fair (a)	Red	13
MY3/014	Murray	Baden Powell (2) Steps	2007-2012	58	560	D	924	205	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Red	13
MY3/018	Murray	Coopers Mill	2009-2012	34	16	A	48	26	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13
MY3/020	Murray	The Clansman	2011-2012	12	470	C	897	187	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Amber	13
MY3/021	Murray	Scarp Pool	2011-2012	12	140	B	149	63	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	13