



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Swan and Canning Rivers

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Decid-egrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
City of Bayswater/ DoBCA	River	EV3/523	Hind Reserve (Garratt Rd - Jetty)	-31.931288, 115.917212	Program	2012-2017	85	140	B	246	67	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) and stormwater samples	13
City of Bayswater/ DoBCA	River	EV3/541	East St Maylands Yacht Club	-31.93723, 115.890928'	Program	2012-2017	89	210	C	9695	169	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) & stormwater samples	13
City of Belmont/ DoBCA	River	EV3/517	Garvey Park (Faulteroy Ave)	-31.921227, 115.942961'	Program	2012-2017	70	290	C	210	91	Very High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of Belmont/ DoBCA	River	EV3/538	Belmont Park Beach	-31.953606, 115.898802'	Program	2012-2017	68	100	B	206	54	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of Belmont/ DoBCA	River	EV3/539	Cracknell Park (Riversdale Rd)	-31.95382, 115.903299'	Program	2012-2017	70	80	B	157	47	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of Canning/ DoBCA	Drain	CA3/013	Riverton Dr E - Drain S boat-ramp	-32.028483, 115.901044'	Point Source	2016-2017	16	4700	D	3469	915	N/A	Not Avail	Red	N/A	
City of Canning/ DoBCA	Drain	CA3/020	Bullcreek Rd Rossmoyne - Drain	-32.045359, 115.861775'	Point Source	2016-2017	15	470	C	320	124	N/A	Not Avail	Amber	N/A	
City of Canning/ DoBCA	Drain	CA3/021	Central Rd Rossmoyne - Drain	-32.038491, 115.86064'	Point Source	2016-2017	16	75	B	138	46	N/A	Not Avail	Green	N/A	
City of Canning/ DoBCA	Drain	CA3/022	First Ave Rossmoyne - Drain	-32.03651, 115.863844'	Point Source	2016-2017	16	90	B	133	51	N/A	Not Avail	Green	N/A	
City of Canning/ DoBCA	Drain	CA3/027	Second Ave Rossmoyne - Drain	-32.031306, 115.870332'	Point Source	2016-2017	16	2	A	22	14	N/A	Not Avail	Green	N/A	

DoBCA = Department of Biodiversity, Conservation and Attractions
MRA = Metropolitan Redevelopment Authority
BOLD* = Final Site Colour



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Swan and Canning Rivers

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Decid-egrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
City of Canning/ DoBCA	River	EV3/542	Shelley Beach Jetty	-32.02758, 115.882444'	Program	2012-2017	64	290	C	705	131	High	Poor	Red	Collect 5-10 rainfall (24-48hrs) & stormwater samples	13
City of Canning/ DoBCA	River	CA3/009	Kent St Weir - US	-32.021215, 115.920948'	Reference	2016-2017	16	210	C	171	76	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
City of Canning/ DoBCA	River	CA3/010	Kent St Weir - DS	-32.021094, 115.92074'	Reference	2016-2017	16	390	C	350	120	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
City of Canning/ DoBCA	River	EV3/547	Clontarf Bay (Cadets)	-32.020882, 115.898649'	Review	2012-2017	74	860	D	1178	275	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of Melville/ DoBCA	River	EV3/505	Bicton Baths	-32.027662, 115.778125'	Program	2012-2017	79	40	A	126	25	Moderate	Good (a)	Green	Collect 5-10 storm-water drain samples	13
City of Melville/ DoBCA	River	EV3/507	Cunningham St (Applecross)	-32.02252, 115.82608'	Program	2012-2017	79	36	A	116	22	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
City of Melville/ DoBCA	River	EV3/532	Point Walter (Kiosk)	-32.011954, 115.78806	Program	2012-2017	79	32	A	86	26	Low	Very Good	Green*	Annual Review	13
City of Melville/ DoBCA	River	EV3/533	Point Walter (Boat Ramps)	-32.012966, 115.790969'	Program	2012-2017	79	55	B	143	33	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) samples	13
City of Melville/ DoBCA	River	EV3/534	Waylen Bay (Scout Hall)	-32.004459, 115.840569'	Program	2012-2017	76	28	A	80	23	Low	Very Good	Green*	Annual Review	13
City of Melville/ DoBCA	River	EV3/540	Deep Water Point (Near Jetty)	-32.022998, 115.854436'	Program	2012-2017	78	26	A	73	24	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13

DoBCA = Department of Biodiversity, Conservation and Attractions
MRA = Metropolitan Redevelopment Authority
BOLD* = Final Site Colour



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Swan and Canning Rivers

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
City of Perth/ DoBCA	River	EV3/528	Hackett Drive Crawley (Kiosk, Jetties)	-31.982554, 115.821613'	Program	2012-2017	48	200	B	662	101	High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of Perth/ DoBCA	River	EV3/530	Hackett Drive Crawley (Tree)	-31.980422, 115.821157'	Program	2012-2017	48	175	B	464	86	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) & stormwater samples	13
City of Perth/ DoBCA	River	EV3/543	Abrahams Reserve Beach	-31.987515, 115.819773'	Program	2012-2017	48	40	A	97	32	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) & stormwater samples	13
City of Perth/ DoBCA	River	PR3/022	Claisebrook	-31.949898, 115.882219'	Program	2012-2017	73	12	A	44	21	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
City of Perth/ DoBCA	River	PR3/023	Trinity	-31.959003, 115.884506'	Program	2012-2017	74	500	C	1252	219	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
City of Perth/ DoBCA	River	PR3/024	Point Fraser	-31.964465, 115.880073'	Program	2012-2017	75	350	C	541	134	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
City of Perth/ DoT	River	PR3/025	Barrack Jetty	-31.960057, 115.858925'	Program	2012-2017	74	40	A	93	32	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
City of Perth/ DoBCA	River	PR3/026	Mounts Bay Road	-31.976211, 115.822666'	Program	2012-2017	74	430	C	772	168	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
City of Perth/ MRA	River	PR3/027	Elizabeth Quay	-31.957467, 115.856181'	Reference	Not Available										5
City of South Perth/ DoBCA	River	EV3/511	Como Beach Jetty	-31.993709, 115.852854'	Program	2012-2017	61	9	A	39	15	Moderate	Good (a)	Green	Collect 5-10 storm-water drain samples	5
City of South Perth/ DoBCA	River	EV3/512	Narrows Bridge	-31.964485, 115.847797'	Program	2012-2017	72	390	C	14723	450	High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13

DoBCA = Department of Biodiversity, Conservation and Attractions
MRA = Metropolitan Redevelopment Authority
BOLD* = Final Site Colour



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Swan and Canning Rivers

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Decid-egrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
City of South Perth/ DoBCA	River	EV3/513	Coode St South Perth	-31.974516, 115.863831'	Program	2012-2017	73	260	C	378	103	Very High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of South Perth/ DoBCA	River	EV3/536	Como Beach South	-31.994324, 115.854664'	Program	2012-2017	65	105	B	258	55	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of South Perth/ DoBCA	River	EV3/537	Como Beach North	-31.99251, 115.854349'	Program	2012-2017	65	260	C	1376	148	Very High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of South Perth/ DoBCA	River	EV3/546	South Perth (Esplanade Beach)	-31.9732, 115.85821'	Program	2012-2017	72	145	B	256	70	High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hr) samples	13
City of Swan/ DoBCA	River	EV3/519	Ray Marshall Park (First Ave)	-31.887731, 115.990672'	Program	2012-2017	56	250	C	239	90	Very High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of Swan/ DoBCA	River	EV3/520	Middle Swan Reserve	-31.863593, 116.007308'	Program	2011-2017	106	660	D	12172	219	Very High	Very poor	Red*		5
City of Swan/ DoBCA	River	SW3/001	Fish Market Reserve – Boat Ramp	-31.898113, 115.959394'	Proposed	<i>Not Available</i>					Moderate	Not Avail	Amber	Collect 5-10 rainfall (24-48hrs) & stormwater samples	5	
Shire of Peppermint Grove	River	EV3/503	Keane St Beach (50M S Irvine St)	-32.000365, 115.771182'	Program	2012-2017	68	350	C	864	267	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Town of Bassendean/ DoBCA	River	EV3/522	Sandy Beach Reserve	-31.922066, 115.951273'	Program	2012-2017	67	460	C	574	156	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
Town of Bassendean/ DoBCA	River	EV3/548	Point Reserve (Nth Jetty)	-31.9041, 115.962751'	Program	2012-2017	66	680	D	458	163	High	Very Poor	Red*	Recommend erect permanent warning sign	5

DoBCA = Department of Biodiversity, Conservation and Attractions
MRA = Metropolitan Redevelopment Authority
BOLD* = Final Site Colour



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Swan and Canning Rivers

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018	
Town of Claremont	River	CL3/001	Swan River - Jetty Rd Jetty	-31.989639, 115.781282'	New	2016-2017	8	170	B	1012	92	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13	
Town of Claremont	River	CL3/002	Swan River - Mrs Herberts Park	-31.991336, 115.786449'	New	2016-2017	8	45	B	92	34	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13	
Town of Claremont	River	CL3/003	Swan River - Claremont Yacht Club	-31.989, 115.779488'	Reference	Not Available											
Town of East Fremantle/ Main Roads	Drain	EF3/009	Main Drain	-32.040772, 115.759911'	Point Source	2016-2017	11	250	C	1648	148	N/A	Not Avail	Amber	N/A	5	
Town of East Fremantle/ DoBCA	River	EV3/545	Preston Point - John Tonkin Park	-32.02903, 115.76196'	Program	2012-2017	37	95	B	700	61	Moderate	Good	Green	Collect 5-10 stormwater drain samples	13	
Town of East Fremantle	River	EF3/012	Fremantle Rowing Club	-32.038981, 115.761166'	New	Not Available										Provide DOH Sanitary Inspection Report	13
Town of East Fremantle	River	EF3/011	Jetty North	-32.038312, 115.761254'	Reference	2016-2017	14	24	A	72	22	Not Avail	Not Avail	Green		5	
Town of Mosman Park/ DoBCA	River	EV3/544	Johnston Street - Hill Tce Beach	-32.003851, 115.772397'	Program	2012-2017	48	3	A	30	18	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5	